



Local
CMS#

CMS# 17036677 HELD/PERMIT

CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order# 1425816982
 Work Activity **Drop-Buried Copper** Capital Maintenance
 Customer Name Sheila Johnson Phone# 763-416-2265
 Address 10557 104th pl N Maple Grove MN One Call Ticket#
 Location/Directions
 Description of Work or Special Instructions Place 3 MST's, Plow ft and Bore

DOR/TOG Yes No Permit: Yes No Bore: Yes No CBR#
 Employee Name : Employee Contact# 612-4303133


Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line					
Ped#					
Parish/County Hennipen					
Township:					
Section					
Range					
GPS Reading					

Nearest cross st. Plat Page Map#

Damaged facility # 124940

SKETCH

Tax Code



Originated By: Evans Date: 1/17/17 Completed By: Date:
 Authorized By: (APS) Date: Inspected By: Date:
 Authorized By: (AOM) Date:
 Inspection notes:
 th PI N