


Revised 5-23-17				CMS#		17115545 PERMIT			
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>									
Company		T600 Exchange		Service Order#					
Work Activity		Drop-Buried Copper			Capital		Maintenance		Y
Customer Name				Nicole Loehr		Phone#		763-420-2976	
Address		18153 70TH Place			One Call Ticket#				
City & Zip		Maple Grove, 55369							
Location/Directions									
Description of Work or Special Instructions									
Held Order									
Y		N		Permit: Y x		Bore: y N		CBR#	
Employee Name		Les Peterson			Employee Contact#		763-807-0943		
Sketch		Material/Labor Units			Footage		Quantity		Comments
(Include Cntr Line & Pedestal)		Description		Notes					
Cntr Line Footage		SEB3-22		BSW 3 pair					
Ped#		109418		SEPCUTOVER		CUTOVER BSW			
Parish/County		Hennepin		BM83		BSW guard at house			
		XXSEB-GL		Remove temp drop					
Township:		BM61(1.25)SEB		BSW Bore footage					
Section		SEBO PER FT LBR		Fiber Drop					
Range		BM2(5/8)(8)		Ground Rod					
		SEB6-22		BSW 6 Pair					
Nearest cross st.					Plat Page		Map#		



Originated By:		Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:		MetroBSW@Centurylink.com					
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			