

Revised 5-3-17				CMS#		17122339 OOS			
CenturyLink BSW Order/Maintenance Work Authorization									
Company	T600	Exchange	PLYMOUTH FERNBROOK			Service Order#	VN773350		
Work Activity	Drop-Buried Copper			Capital		Maintenance	Y		
Customer Name	Cynthia Robeck				Phone#	7635592926			
Address	6316 Upland Ln N				One Call Ticket#				
City & Zip	Maple Grove 55311								
Location/Directions									
Description of Work or Special Instructions									
Held Order		N	Permit:	N	Bore:	Y	CBR#	6123080385	
Employee Name	Jon Strong				Employee Contact#	6125082936			
Sketch <small>(Include Cntr Line & Pedestal)</small>	Material/Labor Units				Footage	Quantity	Comments		
	Description		Notes						
Cntr Line foot#	33	SEB3-22	BSW 3 pair		150				
Ped#		SEPCUTOVER	CUTOVER BSW		Y				
Parish/County		BM83	BSW guard at house		Y				
		XXSEB-GL	Remove temp drop						
Township:		BM61(1.25)SEB	BSW Bore footage		35		Bore under 2 driveways and sidewalk		
Section		SEBO PER FT LBR	Fiber Drop						
Range		BM2(5/8)(8)	Ground Rod						
		SEB6-22	BSW 6 Pair						
Nearest cross st.	Upland and Elm Rd				Plat Page		Map#		



Originated By:	Jon Strong	Date:	6/12/17	Completed By:		Date:	
Authorized By: (APS)	Ulferts, Sarah	Date:	6/13/17	Inspected By:		Date:	
Authorized By: (AOM)	Winberg, Michael	Date:	6/13/17				

Email sketch to: MetroBSW@Centurylink.com

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	