



Local
CMS#

CMS#

17083148


CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order# _____
 Work Activity Drop-Buried Copper Capital x Maintenance _____
 Customer Name Heather Moody Phone# 763-315-4581
 Address 10583 101ST PL N One Call Ticket# _____
 Location/Directions Maple Grove, MN
 Description of Work or Special Instructions plow 200' from Nid to ped w/ 20' bore. Then pick up 300' temp.

DOR/TOG Yes ___ No x Permit: Yes ___ No x Bore: Yes x No ___ CBR# 763-370-8976
 Employee Name Kris Townsend Employee Contact# 612-715-9060

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line _____					
Ped# _____					
Parish/County Hennipen					
Township: _____					
Section _____					
Range _____					
GPS Reading _____					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____ Tax Code _____
SKETCH



Originated By: <u>Townsend</u>	Date: <u>4/20/17</u>	Completed By: _____	Date: _____
Authorized By: (APS) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (AOM) _____	Date: _____	_____	_____

Inspection notes: _____