


Revised 5-23-17				CMS#		17130213 PERMIT			
CenturyLink BSW Order/Maintenance Work Authorization									
Company		T600		Exchange		Osseo		Service Order#	
Work Activity				Capital		Y		Maintenance	
Customer Name		Mellinda Morgan				Phone#		7633150662	
Address		17024 78th Ave N				One Call Ticket#			
City & Zip		Maple Grove MN							
Location/Directions									
Description of Work or Special Instructions				Plow 150 ft from Ped to Nid. One bore of 20 ft					
Held Order		Y		N		Permit:		N	
Employee Name		Don Evans		Bore:		Y		CBR#	
Employee Contact#		6124303133							
Sketch		Material/Labor Units			Footage		Quantity		Comments
(Include Cntr Line & Pedestal)		Description			Notes				
Cntr Line Footage		33		SEB3-22		BSW 3 pair			
Ped#				SEPCUTOVER		CUTOVER BSW			
Parish/County		BM83		XXSEB-GL		Remove temp drop			
Township:		BM61(1.25)SEB				BSW Bore footage			
Section		SEBO PER FT LBR				Fiber Drop			
Range		BM2(5/8)(8)				Ground Rod			
		SEB6-22				BSW 6 Pair			
Nearest cross st.					Plat Page		Map#		



Originated By:	Don Evans	Date:	6/22/17	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:		MetroBSW@Centurylink.com					
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			