


Revised 5-23-17				CMS#		17133678			
CenturyLink BSW Order/Maintenance Work Authorization									
Company		T600		Exchange		Service Order#			
Work Activity				Capital		Y		Maintenance	
Customer Name		Arun Kandy		Phone#		815-668-2264			
Address		11523 82nd Ave N		One Call Ticket#					
City & Zip		Maple Grove MN							
Location/Directions		FIBER DROP FIBER DROP							
Held Order		Y		Permit: Y		Bore: Y		CBR#	
Employee Name		Les Peterson		Employee Contact#		763-807-0943			
Sketch		Material/Labor Units			Footage		Quantity		Comments
(Include Cntr Line & Pedestal)		Description			Notes				
Cntr Line Footage		SEB3-22			BSW 3 pair				
Ped#		SEP CUTOVER			CUTOVER BSW				
Parish/County		Hennepin BM83			BSW guard at house				
		XXSEB-GL			Remove temp drop				
Township:		BM61(1.25)SEB			BSW Bore footage		80		
Section		SEBO PER FT LBR			Fiber Drop		153		
Range		BM2(5/8)(8)			Ground Rod				
		SEB6-22			BSW 6 Pair				
Nearest cross st.		Hemlock Ln			Plat Page		Map#		



Originated By:		Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:		MetroBSW@Centurylink.com					
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			