


Revised 5-23-17				CMS#		17133591			
CenturyLink BSW Order/Maintenance Work Authorization									
Company		T600		Exchange		MAPLE GROVE		Service Order#	
Work Activity				Capital		Y		Maintenance	
Customer Name		SHANEEKA WINFIELD				Phone#		N	
Address		6601 MERRIMAC LN N				One Call Ticket#			
City & Zip		Maple Grove, MN							
Location/Directions		plow 90' from NID to ped. This is fiber. Customer has sprinklers. Cut over fiber when done.							
Description of Work or Special Instructions									
Held Order		N		Permit:		N		Bore:	
Employee Name		Kris Townsend		Employee Contact#		773-899-8092		612-715-9069	
Sketch		Material/Labor Units		Footage		Quantity		Comments	
(Include Cntr Line & Pedestal)		Description		Notes					
Cntr Line Footage		33		SEB3-22		BSW 3 pair			
Ped#				SEPCUTOVER		CUTOVER BSW			
Parish/County		BM83		XXSEB-GL		BSW guard at house			
Township:		BM61(1.25)SEB				Remove temp drop			
Section		SEBO PER FT LBR				BSW Bore footage			
Range		BM2(5/8)(8)				Fiber Drop		90'	
		SEB6-22				Ground Rod			
						BSW 6 Pair			
Nearest cross st.				Plat Page		Map#			



Originated By:	Townsend	Date:	6/26/17	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					