


Revised 5-23-17				CMS#		17133978									
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>															
Company		T600		Exchange		Service Order#									
Work Activity						Capital		Maintenance							
Customer Name		THOMAS MANUS				Phone#		7634241017							
Address		8345 COTTONWOOD LN N				One Call Ticket#									
City & Zip		MAPLE GROVE MN													
Location/Directions															
Description of Work or Special Instructions															
Held Order															
Y		N		Permit: Y		N		Bore: Y		N		CBR#		763-464-0344	
Employee Name		ROY MILLER				Employee Contact#		612-219-9122							
Sketch		Material/Labor Units				Footage		Quantity		Comments					
(Include Cntr Line & Pedestal)		Description		Notes											
Cntr Line Foot#		33		SEB3-22		BSW 3 pair									
Ped#		123509		SEPCUTOVER		CUTOVER BSW		1							
Parish/County		Hennepin		BM83		BSW guard at house		1							
				XXSEB-GL		Remove temp drop		1							
Township:				BM61(1.25)SEB		BSW Bore footage		30		1					
Section				SEBO PER FT LBR		Fiber Drop		120		1					
Range				BM2(5/8)(8)		Ground Rod									
				SEB6-22		BSW 6 Pair									
Nearest cross st.		82ND PLACE N				Plat Page		Map#							



Originated By:	ROY MILLER	Date:	6/26/17	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:		MetroBSW@Centurylink.com					
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			