


CenturyLink BSW Order/Map

Company	T600	Exchange	FERNBROOK	Service Order#	667644136
Work Activity	C67644136		Capital	Maintenance	
Customer Name	BARNARD GLAEFFE			Phone#	404-512-1291
Address	11765 REDFOX DR.			One Call Ticket#	
City & Zip	MARLE GROVE 95369				
Location/Directions	NORTHWEST BLVD & HEMLOCK				
Description of Work or Special Instructions	BAD PAIRS ON BONDED PRISM (LINE IS GND)				

Head Order	Y	(N)	Permit: Y	(N)	Bore: Y	N	CBR#	404-512-1291	
Employee Name	SCOTT ROY			Employee Contact#	612 247-5134				
Sketch	Material/Labor Units			Footage	Quantity	Comments			
(Include Contr Line & Pedestal)	Description	Notes							
Cont# Line foot#	33	SEB3-22	BSW 3 pair						
Part#		SEPCUTOVER	CUTOVER BSW						
Part# Sh/County		BM83	BSW guard at house						
		XXSEB-GL	Remove temp drop						
Township:		BM61(1.25)SEB	BSW Bore footage		20	X 3			
Section		SEBO PER FT LBR	Fiber Drop						
Range		BM2(5/8)(B)	Ground Rod						
		SEB5-22	BSW 6 Pair		430		IF TEMP BORED		
Nearest cross st.	HEMLOCK			Plat Page		Map#			



Originated By:	SCOTT JONES	Date:	7/3/17	Completed By:		Date:	
Authorized By: (APS)	BRANT SANDERS	Date:		Inspected By:		Date:	
Authorized By: (AOM)	MIKE WINDERS	Date:					
Email sketch to:	MetroBSW@Centurylink.com						

- | | | | |
|---|--|---|--|
| 1. Distance of the bury in Right-of-Way | | 3. Distance to the nearest intersection | |
| 2. Distance from the terminal to the centerline | | 4. Nearest State Hwy mile marker | |