


Revised 5-23-17				CMS#		17122896 PERMIT							
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>													
Company		T600		Exchange		Osseo		Service Order#					
Work Activity						Capital		Y		Maintenance			
Customer Name				Dale Walquist				Phone#		6.12352E+11			
Address		10350 Lancaster LN				One Call Ticket#							
City & Zip		Maple Grove MN											
Location/Directions													
Description of Work or Special Instructions				Plow 240 ft from MST to MST to Nid. 3 bores required. Place MST									
Held Order		N		Permit:		N		Bore:		Y		CBR#	
Employee Name		Don Evans				Employee Contact#		6124303133					
Sketch		Material/Labor Units				Footage		Quantity		Comments			
(Include Cntr Line & Pedestal)		Description		Notes									
Cntr Line Footage		33		SEB3-22		BSW 3 pair							
Ped#		124679		SEPCUTOVER		CUTOVER BSW							
Parish/County		BM83		XXSEB-GL		Remove temp drop							
Township:		BM61(1.25)SEB				BSW Bore footage							
Section		SEBO PER FT LBR				Fiber Drop							
Range		BM2(5/8)(8)				Ground Rod							
		SEB6-22				BSW 6 Pair							
Nearest cross st.						Plat Page		Map#					



Originated By:	Don Evans	Date:	7/21/17	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			