


permit

Revised 5-23-17				CMS#		17163291					
CenturyLink BSW Order/Maintenance Work Authorization											
Company		T600		Exchange		Osseo		Service Order#			
Work Activity				Capital		Y		Maintenance			
Customer Name				Joseph Burgess				Phone#		7634160615	
Address		17427 75th Ave N				One Call Ticket#					
City & Zip		Maple Grove MN									
Location/Directions											
Description of Work or Special Instructions											
Held Order		N		Permit:		N		Bore:		Y	
Employee Name		Steve Winch				Employee Contact#		6123870921			
Sketch		Material/Labor Units				Footage		Quantity		Comments	
(Include Cntr Line & Pedestal)		Description		Notes							
Cntr Line Footage		33		SEB3-22		BSW 3 pair					
Ped#		123504		SEPCUTOVER		CUTOVER BSW					
Parish/County		BM83		XXSEB-GL		Remove temp drop					
Township:		BM61(1.25)SEB				BSW Bore footage					
Section		SEBO PER FT LBR				Fiber Drop					
Range		BM2(5/8)(8)				Ground Rod					
		SEB6-22				BSW 6 Pair					
Nearest cross st.						Plat Page		Map#			



Originated By:		Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:		MetroBSW@Centurylink.com					
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			