

Revised 5-23-17		CMS#		17163522 PERMIT	
CenturyLink BSW Order/Maintenance Work Authorization					
Company	T600	Exchange	OSSEO	Service Order#	
Work Activity	Drop-Buried Copper		Capital	N	Maintenance
Customer Name	JEFF BARNES		Phone#	7634940248	
Address	11533 100TH AVE N		One Call Ticket#		
City & Zip	MAPLE GROVE				
Location/Directions	GPS				
Description of Work or Special Instructions	PLACE 255' COPPER DROP WITH 2 20' BORS PICKING UP TEMP DROP IN BACK.				
Held Order	N	Permit:	N	Bore:	Y
Employee Name	MER064519		Employee Contact#	763-228-8645	
Employee Name	MER064519		Employee Contact#	763-228-8645	
CBR#	952-452-4767				
Sketch	Material/Labor Units			Comments	
(Include Cntr Line & Pedes)	Description	Notes	Footage	Quantity	
Cntr Line foot#	33	SEB3-22	BSW 3 pair		
Ped#	545 9011	SEPCUTOVER	CUTOVER BSW		
Parish/County	Hennepin	BM83	BSW guard at house		
		XXSEB-GL	Remove temp drop		
Township:		BM61(1.25)SEB	BSW Bore footage		
Section		SEBO PER FT LBR	Fiber Drop		
Range		BM2(5/8)(8)	Ground Rod		
		SEB6-22	BSW 6 Pair		
Nearest cross st.	GPS		Plat Page	GPS	Map#
				GPS	



Originated By:	MER064519	Date:	8/2/17	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way			3. Distance to the nearest intersection				
2. Distance from the terminal to the centerline			4. Nearest State Hwy mile marker				