


Revised 5-23-17				CMS#		17175169 HELD / PERMIT			
CenturyLink BSW Order/Maintenance Work Authorization									
Company		T600		Exchange		Service Order#			
Work Activity				Capital		Y		Maintenance	
Customer Name				Douglas Lako		Phone#		763-315-2946	
Address		10666 107th Pl		One Call Ticket#					
City & Zip		Maple Grove, mn 55369							
Location/Directions									
Description of Work or Special Instructions				MST PLACEMENT MST PLACEMENT MST PLACEMENT					
Held Order		Y		Permit: Y		Bore: Y		CBR#	
Employee Name		Les Peterson		Employee Contact#		763-807-0943			
Sketch		Material/Labor Units			Footage		Quantity		Comments
(Include Cntr Line & Pedestal)		Description		Notes					
Cntr Line Footage		SEB3-22		BSW 3 pair					
Ped#		320-9032		SEP CUTOVER					
Parish/County		Hennepin		BM83		BSW guard at house			
		XXSEB-GL		Remove temp drop					
Township:		BM61(1.25)SEB		BSW Bore footage					
Section		SEBO PER FT LBR		Fiber Drop					
Range		BM2(5/8)(8)		Ground Rod					
		SEB6-22		BSW 6 Pair					
Nearest cross st.					Plat Page		Map#		



Originated By:		Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:		MetroBSW@Centurylink.com					
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			