


Revised 5-23-17				CMS#		17176116 PERMIT				
CenturyLink BSW Order/Maintenance Work Authorization										
Company		T600		Exchange		OSSEO		Service Order#		MRMN4049444001A00
Work Activity		Buried Cable-Metallic				Capital		Y		Maintenance
Customer Name		JAIME URDINA				Phone#		763-416-0756		
Address		10664 MONTICELLO LN N				One Call Ticket#				
City & Zip		MAPLE GROVE, MN 55369-2755								
Location/Directions										
Description of Work or Special Instructions										
Held Order		N		Permit: Y		Bore: Y		CBR#		612-669-8698
Employee Name		Brandon Smith				Employee Contact#		612-296-7599		
Sketch		Material/Labor Units				Footage		Quantity		Comments
(Include Cntr Line & Pedestal)		Description		Notes						
Cntr Line Footage		33		SEB3-22		BSW 3 pair				
Ped#				SEPCUTOVER		CUTOVER BSW				
Parish/County		BM83		XXSEB-GL		BSW guard at house				
Township:		BM61(1.25)SEB				Remove temp drop				
Section		SEBO PER FT LBR				BSW Bore footage				
Range		BM2(5/8)(8)				Fiber Drop				
		SEB6-22				Ground Rod				
						BSW 6 Pair				
Nearest cross st.						Plat Page		Map#		



Originated By:		Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:		MetroBSW@Centurylink.com					
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			