


Revised 5-23-17				CMS#		17183454 PERMIT	
CenturyLink BSW Order/Maintenance Work Authorization							
Company	T600	Exchange	MAPLE GROVE			Service Order#	MRMN4472444001A00
Work Activity	Buried Cable-Metallic			Capital		Maintenance	
Customer Name	STEPHEN ALO				Phone#	7634164585	
Address	17232 77TH AVE N				One Call Ticket#		
City & Zip	MAPLE GROVE, MN 55311-3751						
Location/Directions							
Description of Work or Special Instructions							
Held Order		N	Permit:	Y	Bore:	Y	CBR# 612-239-3995
Employee Name					Employee Contact#		
Sketch	Material/Labor Units				Footage	Quantity	Comments
(Include Cntr Line & Pedestal)	Description	Notes					
Cntr Line Footage	33	SEB3-22	BSW 3 pair				
Ped#		SEPCUTOVER	CUTOVER BSW		Y		
Parish/County		BM83	BSW guard at house		Y		
		XXSEB-GL	Remove temp drop		Y		
Township:		BM61(1.25)SEB	BSW Bore footage		125'		
Section		SEBO PER FT LBR	Fiber Drop		Y		
Range		BM2(5/8)(8)	Ground Rod				
		SEB6-22	BSW 6 Pair				
Nearest cross st.					Plat Page	Map#	



Originated By:		Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					