


CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order#
 Work Activity Drop-Buried Copper JIBER Capital X Maintenance *
 Customer Name JORDAN MACK Phone# 763-416-2159
 Address 10144 Boundary Creek Ln
 Location/Directions Maple Grove, MN
 Description of Work or Special Instructions

DOR/TOG Yes ___ No x Permit: Yes ___ No x Bore: Yes X No * Employee Contact# joe.vukelich
 Employee Name Joe Vukelich CBR# 612-499-1044

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line					
Ped#					
Parish/County Hennipen					
Township:					
Section					
Range					
GPS Reading					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____



Originated By: JOE VUKELICH Date: 6/28/10 Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Inspection notes: _____