


Revised 5-23-17				CMS#		17183782 HELD ORDER PERMIT				
CenturyLink BSW Order/Maintenance Work Authorization										
Company		T600	Exchange		Osseo			Service Order#		
Work Activity					Capital	Y	Maintenance			
Customer Name		Sean Daniels				Phone#				
Address		9901 101st Place N			One Call Ticket#					
City & Zip		Maple Grove MN								
Location/Directions		Place MST								
Description of Work or Special Instructions										
Held Order		Y	Permit:	Y	Bore:	Y	CBR#		6128037174	
Employee Name		Don Evans			Employee Contact#		6124303133			
Sketch		Material/Labor Units			Footage	Quantity	Comments			
(Include Cntr Line & Pedestal)		Description	Notes							
Cntr Line Footage	33	SEB3-22	BSW 3 pair							
Ped#		SEP CUTOVER	CUTOVER BSW							
Parish/County		BM83	BSW guard at house							
		XXSEB-GL	Remove temp drop							
Township:		BM61(1.25)SEB	BSW Bore footage							
Section		SEBO PER FT LBR	Fiber Drop							
Range		BM2(5/8)(8)	Ground Rod							
		SEB6-22	BSW 6 Pair							
Nearest cross st.		Nathan Ln			Plat Page		Map#			



Originated By:	Don Evans	Date:	8/29/17	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:		MetroBSW@Centurylink.com					
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			