


Revised 5-23-17				CMS#	17194880 HELD PERMIT				
CenturyLink BSW Order/Maintenance Work Authorization									
Company	T600	Exchange				Service Order#	MRMN4034908001G00		
Work Activity				Capital		Maintenance			
Customer Name	MOLLY REDENBO					Phone#	7634161471		
Address	7751 GARLAND LN N					One Call Ticket#			
City & Zip	MAPLE GROVE MN								
Location/Directions									
Description of Work or Special Instructions				DO NOT PLOW A SERVICE TO HOUSE.					
Held Order	Y	Permit:	Y	Bore:	Y	CBR#	309-678-4948		
Employee Name	ROY MILLER			Employee Contact#	612-219-9122				
Sketch	Material/Labor Units			Footage	Quantity	Comments			
(Include Cntr Line & Pedestal)	Description	Notes							
Cntr Line Footage	33	SEB3-22	BSW 3 pair						
Ped#	1172-9010	SEPCUTOVER	CUTOVER BSW						
Parish/County	Hennepin	BM83	BSW guard at house			1			
		XXSEB-GL	Remove temp drop						
Township:		BM61(1.25)SEB	BSW Bore footage		30	3			
Section		SEBO PER FT LBR	Fiber Drop		350	1	4 PORT MST		
Range		BM2(5/8)(8)	Ground Rod						
		SEB6-22	BSW 6 Pair						
Nearest cross st.	78TH AVE N			Plat Page		Map#			



Originated By:		Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					