


Revised 5-23-17				CMS#		17200353 PERMIT			
CenturyLink BSW Order/Maintenance Work Authorization									
Company		T600 Exchange		Service Order#			TRMN000116329900		
Work Activity		Capital			Maintenance				
Customer Name				A K BUILDING MAINTENANCE			Phone#		
Address				7350 KIMBERLY LN N			One Call Ticket#		
City & Zip				MAPLE GROVE MN					
Location/Directions				Place 4 port MST and place drop to house.					
Description of Work or Special Instructions									
Held Order		N		Permit: Y		Bore: Y		CBR#	
Employee Name		Roy Miller			Employee Contact#		612-219-6122		
Sketch		Material/Labor Units			Footage		Quantity		Comments
(Include Cntr Line & Pedestal)		Description			Notes				
Cntr Line Foot#		33			SEB3-22		BSW 3 pair		
Ped#		123645			SEPCUTOVER		CUTOVER BSW		
Parish/County		Hennepin			BM83		BSW guard at house		
					XXSEB-GL		Remove temp drop		
Township:					BM61(1.25)SEB		BSW Bore footage		35 2
Section					SEBO PER FT LBR		Fiber Drop		55 1 200 Foot 4 Port MST
Range					BM2(5/8)(8)		Ground Rod		
					SEB6-22		BSW 6 Pair		
Nearest cross st.		73rd PL N			Plat Page		Map#		



Originated By:	Roy Miller	Date:	9/19/17	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			