


Revised 5-23-17				CMS#		17200581 PERMIT			
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>									
Company		T600		Exchange		Service Order#			
Work Activity		Drop-Buried Copper				Capital		Y	
Customer Name		Alicia Convet		Maintenance		N			
Address		10811 Wellington Ln N				Phone#		763-315-1253	
City & Zip		Maple Grove MN 55369							
Location/Directions									
Description of Work or Special Instructions		FIBER DROP FIBER DROP FIBER DROP							
Held Order		Y		N		Permit: Y		N	
Employee Name		Les Peterson				Employee Contact#		763-807-0943	
Sketch		Material/Labor Units			Footage		Quantity		Comments
(Include Cntr Line & Pedestal)		Description			Notes				
Cntr Line Footage		SEB3-22			BSW 3 pair				
Ped#		114995			SEPCUTOVER		CUTOVER BSW		
Parish/County		Hennepin			BM83		BSW guard at house		
		XXSEB-GL			Remove temp drop				
Township:		BM61(1.25)SEB			BSW Bore footage				
Section		SEBO PER FT LBR			Fiber Drop				
Range		BM2(5/8)(8)			Ground Rod				
		SEB6-22			BSW 6 Pair				
Nearest cross st.		108th Ave N				Plat Page		Map#	



Originated By:		Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:		MetroBSW@Centurylink.com					
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			