

Revised 5-23-17		CMS#		17207801 PERMIT	
CenturyLink BSW Order/Maintenance Work Authorization					
Company	T600	Exchange	OSSEO	Service Order#	1461074537
Work Activity				Capital	Y
Customer Name	MST PLACEMENT			Maintenance	N
Address	10716 103RD PL N			Phone#	NA
City & Zip	MAPLE GROVE			One Call Ticket#	
Location/Directions	GPS				
Description of Work or Special Instructions	PLACE A 275' 4 PORT MST TO SERVE 3 CUSTOMER WITH 2 20' DW BORES AND A 35' ROAD BORE				
Held Order	Y	Permit:	Y	Bore:	Y
Employee Name	MER064519			Employee Contact#	763-228-8645
Employee Name	MER064519			Employee Contact#	763-228-8645
CBR#	612-834-9493 (MONICA)				
Sketch	Material/Labor Units			Footage	Quantity
(Include Cntr Line & Pedes)	Description	Notes			Comments
Cntr Line foot	33	SEB3-22	BSW 3 pair		
Ped#	IMS1	SEP CUTOVER	CUTOVER BSW		
Parish/County	Hennepin	BM83	BSW guard at house		
		XXSEB-GL	Remove temp drop		
Township:		BM61(1.25)SEB	BSW Bore footage		
Section		SEBO PER FT LBR	Fiber Drop		
Range		BM2(5/8)(8)	Ground Rod		
		SEB6-22	BSW 6 Pair		
Nearest cross st.	GPS			Plat Page	GPS
				Map#	GPS



Originated By:	MER064519	Date:	9/27/17	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			