

| | | | | | |
|--|----------------------|-----------------|--------------------|----------------------|-------------|
| Revised 5-23-17 | | CMS# | | 17214349 PERMIT RUSH | |
| CenturyLink BSW Order/Maintenance Work Authorization | | | | | |
| Company | T600 | Exchange | MAPLE GROVE | Service Order# | na |
| Work Activity | Drop-Buried Copper | | Capital | N | Maintenance |
| Customer Name | JOHN GRASSMANN | | Phone# | 7634204210 | |
| Address | 14000 75TH PL N | | One Call Ticket# | na | |
| City & Zip | MAPLE GROVE, MN | | | | |
| Location/Directions | GPS | | | | |
| Description of Work or Special Instructions | | | | | |
| place 170' copper drop with drive way bores. | | | | | |
| Held Order | N | Permit: | Y | Bore: | Y |
| Employee Name | MER064519 | | Employee Contact# | 763-228-8645 | |
| Sketch | Material/Labor Units | | | Comments | |
| (Include Cntr Line & Pedes) | Description | Notes | Footage | Quantity | |
| Cntr Line foot | 33 | SEB3-22 | BSW 3 pair | | |
| Ped# | term | SEP CUTOVER | CUTOVER BSW | | |
| Parish/County | Hennepin | BM83 | BSW guard at house | | |
| | | XXSEB-GL | Remove temp drop | | |
| Township: | | BM61(1.25)SEB | BSW Bore footage | | |
| Section | | SEBO PER FT LBR | Fiber Drop | | |
| Range | | BM2(5/8)(8) | Ground Rod | | |
| | | SEB6-22 | BSW 6 Pair | | |
| Nearest cross st. | GPS | | Plat Page | GPS | Map# |
| | | | | GPS | |



| | | | | | | | |
|---|--------------------------|-------|---|---------------|--|-------|--|
| Originated By: | MER064519 | Date: | 10/5/17 | Completed By: | | Date: | |
| Authorized By: (APS) | | Date: | | Inspected By: | | Date: | |
| Authorized By: (AOM) | | Date: | | | | | |
| Email sketch to: | MetroBSW@Centurylink.com | | | | | | |
| 1. Distance of the bury in Right-of-Way | | | 3. Distance to the nearest intersection | | | | |
| 2. Distance from the terminal to the centerline | | | 4. Nearest State Hwy mile marker | | | | |