


Revised 5-23-17				CMS#		17205595 PERMIT	
CenturyLink BSW Order/Maintenance Work Authorization							
Company	T600	Exchange	OSSEO	Service Order#			
Work Activity	Drop-Buried Copper			Capital	N	Maintenance	Y
Customer Name				Phone#			
Address	10468 Yorktown Ln N			One Call Ticket#			
City & Zip	Maple Grove 55369						
Location/Directions	off 105th and Zachary						
Description of Work or Special Instructions							
Held Order	Y	N	Permit:	Y	N	Bore:	Y
Employee Name	Dexter Koopp			Employee Contact#	851-392-5304		
Sketch	Material/Labor Units			Footage	Quantity	Comments	
(Include Cntr Line & Pedestal)	Description			Notes			
CNTR Line Tools	33	SEB3-22	BSW 3 pair				
PEOD#	123918	SEP	CUTOVER			1	
Parish/County	Hennepin	BM83	BSW guard at house				
		XXSEB-GL	Remove temp drop			1	
Township:		BM61(1.25)SEB	BSW Bore footage				
Section		SE60 PER FT LBR	Fiber Drop		1	215	
Range		BM2(5/8)B	Ground Rod				
		SEB5-22	BSW 6 Pair				
Nearest cross st.	105th Ave			Plat Page	Map#		

215 FOOT FIBER DROP(NO BORES)



Originated By:	Dexter Koopp	Date:	10/17/17	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	