
Node Pesign Comcast Track

JT 19853

Issued 7/18/14 T-Ray Ub 162'

Plant Maintenance Requ	est V5		Job number	NW369
Node dc171	City	maple grove	Date	7/28/2016
Address 12	160 101st ave n	Cross	Street	ives way
Maint tech Name:	Shane Husbyn	Tech #	1342 Phone:	651-387-4988
Span type span (tempo	ed) Span (no temp)	Digup (Other Spring	
Priority 1 🛂 a.) Cust	omer Impacting Issue b.) Vuln	nerabe temp c.) TIE rela	ated ticket	7
2 🔲 a.) Aeria	ıl temp cables b.) Any temp - r	no liability issues		
3 🗌 a.) Ident	tified cables - no customer imp	oact b.) Leaks - no cust	omer impact	
Work is needed: 🕡 🗚			XC_1);	
Work is a : 🔽 Cable Repla			er Damaged Ped	
Utility	/ Violation Storm Damag	ge 🗌 Leakage	Other	
MDU? (Attachments, loci			No	
Type of Cable			Siz	e: <u>625</u>
Footage: Aerial		Underground	162'	
Bore Required Yes No If yes, what type and how many 2 driveways front easement				
Is there fiber in the packa	nge? ∐ Yes ☑ No	How Many Fiber	rs?	_
Cause for referral: 🗸 F	RTM Leakage Rapid	Resolve (Flux)	Damage/Outage	NH/MH LPI
_		rvice Call Alert		Other CM Suckout
Explain Damage: multiple faults . Need spa	ın replaced asap. Temp	laying in street		
				ž
	<u>Mainte</u>	nance Departme		
Date Received		— Capitol	Yes No	Maint complete $\ igsqcup$
Total Tech Hours		Techs		
	A Highlighted	plant map must b	e attached	
To help expedite this mai	ntenance request, infor	mation on this for	m needs to be fill	ed out completely and
signed by a technician an	d a supervisor requestir	ng the repair.		
Tech Signature	Shane Husbyn	Ted	ch# 134	2 Date 7/28/2016
Supervisor Signature			-	
.		uction Departme	nt Use Only	
Date received	Project #			Construction Completed
Coordinator Signature		Supervisor Sigr	nature	



100 h (h P DESERVE GAIN COURS PW WITH ERE AARAAAAA

TESTWIZARD