


Revised 5-23-17				CMS#		18005236	
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>							
Company		T600	Exchange		MAPLE GROVE	Service Order# 1476340967	
Work Activity				Capital		Maintenance	
Customer Name		SONG CHUNG				Phone# 7634162068	
Address		17154 77TH AVE N		One Call Ticket#			
City & Zip		Maple Grove MN					
Location/Directions							
Description of Work or Special Instructions				place 2 port MST between address 17132 and 17154, 2nd MST goes in between 17186 and 17208.			
Held Order		Y	N	Permit: Y N		Bore: Y N	
Employee Name		Roy Miller		Employee Contact#		612-219-9122	
Sketch		Material/Labor Units		Footage		Quantity	
(Include Cntr Line & Pedestal)		Description		Notes		Comments	
Cntr Line Footage	33	SEB3-22	BSW 3 pair				
Ped#	114639	SEPCUTOVER	CUTOVER BSW				
Parish/County	Hennepin	BM83	BSW guard at house				
		XXSEB-GL	Remove temp drop				
Township:		BM61(1.25)SEB	BSW Bore footage				
Section		SEBO PER FT LBR	Fiber Drop				
Range		BM2(5/8)(8)	Ground Rod				
		SEB6-22	BSW 6 Pair				
Nearest cross st.	garland ave N		Plat Page		Map#		



Originated By:	Roy Miller	Date:	1/5/18	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			