


LOCAL	Exch#	Fernbrook WC	CMS#	
CenturyLink BSW Order/Maintenance Work Authorization				
Company	1800	Exchange	763-553	Service Order#
Work Activity		Capital		Maintenance <input checked="" type="checkbox"/>
Customer Name	Gregory Olson			Phone#
Address	12130 62nd Ave N			763-551-1427
City & Zip	Maple Grove			55369
Location/Directions				
Description of Work or Special Instructions	BSW			
Hold Order?	NO	Permit	N	No
Employee Name	Jason Archuleta			Employee Contact#
Sketch	Material/Labor Units		Est Qty	Actual Qty
Include Cntr, Line & Pedestal	Description		Notes	
CNT LINE 1802	SEB8-22	Place 3 pair BSW	130	130'
Ped#	SEPCUTOVER	CUTOVER BSW	1	
Parish/County	BM83	BSW guard at house	1	
Township	XXSEB-GL	Remove temp drop	150	
Secotr	BM61(1.5)D	BSW bore required	25'	Driveway
Range	SEB3-22T	Hand Dig	-	
	SEBOPZ	Fiber Drop	-	
Nearest cross st.	62nd Ave & Kirkwood Ln		Plat Page	Map#
Damaged facility #				
SKETCH				



Originated By:	Jason Archuleta	Date:	6-23-16	Completed By:		Date:	
Authorized By: (APS)	James	Date:	6-27	Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Inspection Notes:	MetroBSW@centurylink.com						
1. Distance of the bury in Right-of-Way							
3. Distance to the nearest intersection							