


Revised 5-23-17				CMS#		18029259			
CenturyLink BSW Order/Maintenance Work Authorization									
Company		T600		Exchange		Service Order#			
Work Activity						Capital		Maintenance	
Customer Name		Kristen Vetter						N	
Address		17338 66TH PL N				Phone#		763-773-3311	
City & Zip		Maple Grove							
Location/Directions									
Description of Work or Special Instructions		plow 200'. This is fiber. Pick up 300' temp when done and cut over 40' bore							
Held Order		N		Permit: y		Bore: y		CBR#	
Employee Name		Kris Townsend				Employee Contact#		612-715-9069	
Sketch		Material/Labor Units				Footage		Quantity	
(Include Cntr Line & Pedestal)		Description		Notes				Comments	
Cntr Line Footage		33		SEB3-22		BSW 3 pair			
Ped#				SEPCUTOVER		CUTOVER BSW			
Parish/County		BM83		XXSEB-GL		BSW guard at house			
Township:		BM61(1.25)SEB				Remove temp drop			
Section		SEBO PER FT LBR				BSW Bore footage			
Range		BM2(5/8)(8)				Fiber Drop			
		SEB6-22				Ground Rod			
						BSW 6 Pair			
Nearest cross st.						Plat Page		Map#	



Originated By:	Townsend	Date:	2/15/18	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			