

Revised 5-23-17		CMS#	18044058	
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>				
Company	T600	Exchange	MAPLE GROVE	
Work Activity	Buried Cable-Metallic		Capital	Y
Customer Name			Maintenance	
Address	9658 105th Ave N.		Phone#	
City & Zip	Maple Grove 55369		One Call Ticket#	
Location/Directions				
Description of Work or Special Instructions	Plow drop			

Held Order	Y	Permit:	Y	Bore:	Y	CBR#	
Employee Name	Brandon Smith			Employee Contact#	612-296-7599		
Sketch	Material/Labor Units			Footage	Quantity	Comments	
(Include Cntr Line & Pedestal)	Description	Notes					
Cntr Line Footage	33	SEB3-22	BSW 3 pair		N		
Ped#		SEPCUTOVER	CUTOVER BSW		N		
Parish/County		BM83	BSW guard at house		Y		
		XXSEB-GL	Remove temp drop		N		
Township:		BM61(1.25)SEB	BSW Bore footage		40'		
Section		SEBO PER FT LBR	Fiber Drop		Y		
Range		BM2(5/8)(8)	Ground Rod		N		
		SEB6-22	BSW 6 Pair		N		
Nearest cross st.				Plat Page		Map#	

Held order - on hold until spring!



Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					