


16158792 PERMIT

Local Exchange **Fernbrook NE**

CenturyLink BSW Order/Maintenance Work Authorization

Company: T800 Exchange: **763 553** Service Order#: **T46612507**
 Work Activity: **BSW** Capital Maintenance
 Customer Name: **Tracy Reivks** Phone#: **763 559 1875**
 Address: **11746 N 65th Place N**
 City & Zip: **Maple Grove 55369**

Description of Work or Special Instruct:			
Hold Order?	<input checked="" type="checkbox"/> Permit	<input checked="" type="checkbox"/> Bond	NO
Employee Name	Jason Archuleta		Employee Contact# 612 270 9612
Sketch	Material/Labor Units	Est Qty	Actual Qty
(Include Cntr Line & Parcel)	Description	Notes	Placed by (Foreman/Crew Name)
Cntr Line for	SEB3-22	Place 3 pair BSW	325'
Pad#	SEP CUTOVER	CUTOVER BSW	1
County	BM83	BSW guard at house	1
Township:	XXSEB-GL	Remove temp drop	600
Section	BM61(1.5)D	BSW Bore required	40' (2) driveways
Range	SEB3-22T	Hand Dig	
	SEBOP2	Fiber Drop	
Nearest cross st.		Plat Page	Map#
Damaged facility #			



Originalled By: **Jason Archuleta** Date: **7-18-16** Completed By: _____ Date: _____
 Authorized By: **James** Date: **7-25** Inspected By: _____ Date: _____
 Inspection Notes: MetroBSW@centurylink.com

1. Distance of the bury in Right-of-Way _____
 2. Distance from the terminal to the centerline _____
 3. Distance to the nearest Intersection _____
 4. Nearest State Hwy mile marker _____