Revised 5-	23-17		CMS#		18055825				
		CenturyLink BS	SW Orde	er/Mainte	enan	ce Work Autho	rization		
Company	T600 Exchange OS	SEO				Service Order#			
Work Activity			Capit	al	Υ	Mainten	ance		
Customer Name	Paul Lorenz					Phone#		734252003	
Address	10782 Lancaster Ln N			One (One Call Ticket#				
City & Zip	Maple Grove MN								
Location/Directions									
Description of Work or Sp	pecial Instructions Pla	w 360 ft FIBER from ped to	o nid. 4 b	ores requir	ed				
	•	•		<u> </u>					
Held Order	Y Permit: Y	Bore: Y				CBR# <mark>7634252003</mark>			
Employee Name	Don Evans		Employe	Employee Contact#		6124303133			
Sketch	Material/Labor	Units				Comments			
(Include Cntr Line & Pedestal)	Description	Notes	Footage						
Cntr Line foota 33	SEB3-22	BSW 3 pair							
Ped#	SEPCUTOVER	CUTOVER BSW							
Parish/County	BM83	BSW guard at house							
	XXSEB-GL	Remove temp drop	Remove temp drop						
Township:	BM61(1.25)SEB	BSW Bore footage							
Section	SEBO PER FT LBR	Fiber Drop							
Range	BM2(5/8)(8)	Ground Rod							
	SEB6-22	BSW 6 Pair							
Nearest cross st.						Map#			



Held order - on hold until spring!

Originated By:	Don Evans		Date:	4/2/18	Completed By:		Date:	
Authorized By: (APS)			Date:		Inspected By:		Date:	
Authorized By: (AOM)			Date:		_			
Email sketch to:		MetroBSV	V@Centur	rylink.con	า			
Distance of the bury in Right-of-Way				3. Distance to	the nearest intersection			
2. Dictance from the terminal to the conterline				4 Noarost Sta	to Husy mile marker	1		