



Local
CMS#

16184225 OOS PERMIT


CenturyLink Constant Job Order/Maintenance work Authorization

Company T866 Exchange 579 Osseo Service Order# _____
 Work Activity Drop-Buried Copper Capital x Maintenance _____
 Customer Name Victor Leonovich Phone# 763-416-0600
 Address 17005 76th. Av. N., Maple Grove One Call Ticket# _____
 Location/Directions _____
 Description of Work or Special Instructions _____

DOR/TOG Yes ___ No x Permit: Yes x No ___ Bore: Yes X No X CBR# 763-670-5192
 Employee Name Brandon Smith Employee Contact# 612-296-7599

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line					
Ped#					
Parish/County					
Hennipen					
Township:					
Section					
Range					
GPS Reading					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____ Tax Code _____
 SKETCH _____



Originated By: _____	Date: _____	Completed By: _____	Date: _____
Authorized By: (APS) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (AOM) _____	Date: _____		
Inspection notes: _____			