

Revised 5-23-17		CMS#		18023805	
CenturyLink BSW Order/Maintenance Work Authorization					
Company	T600	Exchange	MAPLE GROVE	Service Order#	
Work Activity				Capital	Y
Customer Name	BRITTNEE ALEXANDER			Maintenance	N
Address	9750 104TH AVE N			Phone#	7634164505
City & Zip	MAPLE GROVE			One Call Ticket#	
Location/Directions	GPS				
Description of Work or Special Instructions	SEE SKETCH FOR DETAILS				
Held Order	Y	Permit:	Y	Bore:	Y
Employee Name	MER064519			Employee Contact#	763-228-8645
Sketch	Material/Labor Units			Footage	Quantity
(Include Cntr Line & Pedes)	Description	Notes			Comments
Cntr Line foot#	33	SEB3-22	BSW 3 pair		
Ped#	MS1	SEP/CUTOVER	CUTOVER BSW		
Parish/County	Hennepin	BM83	BSW guard at house		
		XXSEB-GL	Remove temp drop		
Township:		BM61(1.25)SEB	BSW Bore footage		
Section		SEBO PER FT LBR	Fiber Drop		
Range		BM2(5/8)(8)	Ground Rod		
		SEB6-22	BSW 6 Pair		
Nearest cross st.	GPS			Plat Page	GPS Map# GPS

Held order - wait until spring!



Originated By:	MER064519	Date:	2/6/18	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker