


Revised 5-23-17				CMS#		17256696	
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>							
Company		T600	Exchange		MAPLE GROVE	Service Order#	
Work Activity					Capital	Maintenance	
Customer Name				Sriniva Rupireddy		Phone# 7634204961	
Address		6877 Peony Ln N			One Call Ticket#		
City & Zip		Maple Grove MN					
Location/Directions							
Description of Work or Special Instructions				Plow 250 ft from pred to Nid. Bore 20 ft. Pick up temp drop			
Held Order		N	Permit:	N	Bore:	Y	CBR# 6129985945
Employee Name		Don Evans			Employee Contact#		6124303133
Sketch		Material/Labor Units			Footage	Quantity	Comments
(Include Cntr Line & Pedestal)		Description		Notes			
Cntr Line Footage	33	SEB3-22		BSW 3 pair			
Ped#		SEPCUTOVER		CUTOVER BSW			
Parish/County		BM83		BSW guard at house			
		XXSEB-GL		Remove temp drop			
Township:		BM61(1.25)SEB		BSW Bore footage			
Section		SEBO PER FT LBR		Fiber Drop			
Range		BM2(5/8)(8)		Ground Rod			
		SEB6-22		BSW 6 Pair			
Nearest cross st.					Plat Page	Map#	



Originated By:	Don Evans	Date:	12/14/17	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:		MetroBSW@Centurylink.com					
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			