


Revised 5-23-17				CMS#		18013575 PERMIT					
CenturyLink BSW Order/Maintenance Work Authorization											
Company		T600		Exchange		OSSEO		Service Order#		1477260207	
Work Activity						Capital	Y	Maintenance	N		
Customer Name		PATRICK LEWIS						Phone#		763-424-0465	
Address		10503 103RD AVE N						One Call Ticket#			
City & Zip		MAPLE GROVE 55369									
Location/Directions		CORNER OF 103RD AND BOUNDARY CREEK									
Description of Work or Special Instructions		PLACE FIBER DROP									
Held Order		Y		Permit:	Y		Bore:	N		CBR#	651-307-4523
Employee Name		Dexter Koopp				Employee Contact#				651-302-5304	
Sketch		Material/Labor Units				Footage	Quantity	Comments			
(Include Cntr Line & Pedestal)		Description		Notes							
Cntr Line Footage		33	SEB3-22	BSW 3 pair							
Ped#			SEPCUTOVER	CUTOVER BSW			1				
Parish/County		Hennepin	BM83	BSW guard at house			1				
			XXSEB-GL	Remove temp drop			1				
Township:			BM61(1.25)SEB	BSW Bore footage							
Section			SEBO PER FT LBR	Fiber Drop		350	1				
Range			BM2(5/8)(8)	Ground Rod							
			SEB6-22	BSW 6 Pair							
Nearest cross st.		BOUDARY CREEK				Plat Page		Map#			



Originated By:	Dexter Koopp	Date:	1/18/18	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way				3. Distance to the nearest intersection			
2. Distance from the terminal to the centerline				4. Nearest State Hwy mile marker			