



Local
CMS#

CMS# 16190421 Held Order Permit


CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order# _____
 Work Activity Drop-Buried Copper Capital x Maintenance _____
 Customer Name Justin Rohloff Phone# 763-420-1394
 Address 16864 78 AVE N One Call Ticket# _____
 Location/Directions Maple Grove, MN
 Description of Work or Special Instructions plow 155; from NID to ONU, with 2 bores at 25' each.

DOR/TOG Yes ___ No x Permit: Yes ___ No x Bore: Yes x No ___ CBR# 320-287-0470
 Employee Name Kris Townsend Employee Contact# 612-715-9060

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line _____					
Ped# _____					
Parish/County Hennipen					
Township: _____					
Section _____					
Range _____					
GPS Reading _____					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____ Tax Code _____
SKETCH |
-N-
|



Originated By: Townsend Date: 8/23/16 Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Inspection notes: _____