

Local Exch#		CMS#		16188504 Permit	
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>					
Company	T600	Exchange	Service Order#		1393907247
Work Activity			Capital	Y	Maintenance N
Customer Name	KYLE ROBINSON		Phone#	763-424-1232	
Address	11882 84TH TERR N		One Call Ticket#		
City & Zip	MAPLE GROVE				
Location/Directions	GPS				
Description of Work or Special Instructions					
CONDIT NOT PRE-PLACED DURING CONSTRUCTION. PLACE 125' FIBER DROP WITH 3 16' DW BORES					
Held Order ?	NO	Permit:	NO	Bore:	NO
				CBR#	760-458-8228
Employee Name	MER064519		Employee Contact#	7632288645	
Material/Labor Units			Est	Actual	Placed by
(Include Cntr Line & Pedestal)	Description	Notes	Qty.	Qty	(Foreman/Crew Name)
Cntr Line foot#	33	SEB3-22	Place 3 pair BSW		
Ped#	122739	SEPCUTOVER	CUTOVER BSW		
Parish/County	Hennepi	BM83	BSW guard at house		
		XXSEB-GL	Remove temp drop		
Township:	na	BM61(1.5)D	BSW Bore required		
Section	na	SEB3-22T	Hand Dig		
Range	na	SEBOP2	Fiber Drop		
Nearest cross st.	GPS		Plat Page	GPS	Map# GPS
Damaged facility #					
<b>SKETCH</b>					



Originated By:	MER064519	Date:	8/22/16	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Inspection Notes:		MetroBSW @centurylink.com					
1.	Distance of the bury in Right-of-Way		3.	Distance to the nearest intersection			
2.	Distance from the terminal to the centerline:		4.	Nearest State Hwy mile marker			