

Revised 5-23-17

17258114 PERMIT



CenturyLink BSW O&M Maintenance Work Authorization

Company	T600	Exchange	Fernbrook 763-553	Service Order#	176370114
Work Activity	Inst New 3PR BSW Damage Temp			Capital	Maintenance
Customer Name	Nordberg Inc Vor			Phone#	763-519-1378 Bond 1
Address	11773 Red Fox Dr			One Call Ticket#	763-559-5244 Bond 2
City & Zip	Maple Grove				
Location/Directions					

Description of Work or Special Instructions: Inst New 3PR BSW from Ped to SNI Remove Temp

Held Order	Y	<input checked="" type="checkbox"/>	Permit	Y	N	Bore	Y	N	CBR#	763-670-0306
Employee Name	E Janga				Employee Contact#					
Sketch	Material/Labor Units									
(Include Cntr Line & Pedestal)	Description	Notes	Footage	Quantity	Comments					
Cntr Line foot#	33	SEB3-22	BSW 3 pair	240						
Ped#	SEPCUTOVER		CUTOVER BSW							
Parish/County	BM83	BSW guard at house								
	XXSEB-GL	Remove temp drop		150						
Township:	BM61(1.25)SEB	BSW Bore footage		50	2 driveway Bore					
Section	SEBO PER FT LBR	Fiber Drop								
Range	BM2(5/8)(8)	Ground Rod								
	SEB6-22	BSW 6 Pair								
Nearest cross st.	Hemlock Ln + Red Fox Dr			Plat Page	1 F101	Map#	Hudson	Large Print		

Remove Temp from SNI to 11765 Red Fox DR BSW  
 Place New 3PR BSW from SNI to PED AT F11789 RFB



Red Fox DR  
 2 Drive way Bores 24ft + 30ft  
 11781 11789

11789  
 PR 133 O-R, R-G  
 PR 137 O-R, BIK-O

Originated By:	Ed	Date:	12/18	Completed By:		Date:	
Authorized By: (APS)	Soren	Date:	12/18	Inspected By:		Date:	
Authorized By: (AOM)	Mike	Date:	12/18				
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	