

MGCH# 18-3737



Surface Disturbed at Main

Concrete

Bituminous

Oiled

Other \_\_\_\_\_

Boulevard

Basement

Yes  No

Building

Old  New

Coatings

Steel Pipe:

Cor-Bond

Scotchkote #202

X-Thru-Coat

Coal Tar Enamel

Flexclad

Other Alloy A

Fittings:

Black Mastic

Plastic Tape

Valve in Roadway Cover

Yes  No

Type \_\_\_\_\_ Size \_\_\_\_\_

Valve loc. Blvd.  Str.

Main loc. Blvd.  Str.

\_\_\_\_\_ ft. \_\_\_\_\_

\_\_\_\_\_ ft. \_\_\_\_\_

Casing

Yes  No

Show casing on sketch

Soil clay

Service Location

Right

Left

Front