

MGC# 18-3933

CASING USED 1 yes 2 no

- Thru Wall
- Under Floor
- Under Aseway-Drive
- Vented
- Other

NOTE: Show Casing on sketch

Basement yes no

Building Old New

Fittings) No oxide

Ceased with) plastic tape

VALVE LOCATION


- R/w cover at Curb
- R/w cover at Main
- Buried at Main
- Other

Ft. _____

Ft. _____

Revere LN N

95 Ave N



2' SET BACK
5' SWEEP BEND

main Loc 25' E &

43'

59'

47'



Maple Grove

94 AVE. N.

Conditions in yard (Mark only one) 1 No Sod 2 Sod 3 Solid pavement

Obstacles 1 None 2 Concrete Sidewalk or Curb 3 Other, specify _____

Soil (Mark only one) 1 Peat or Loam 2 Sand 3 Clay 4 Gravel 5 Rock or Fill

Method of ditching. Ditcher: 1 Used all the way 2 Used partly 3 Not used

Sq. ft. of Sod moved or replaced NONE Sq. ft. (Enter Sq. ft. or write none)

Paving 1 Concrete 2 Bituminous: Permanent

3 Oiled: Non Permanent 4 Other - Not paved

Paving in Street, size disturbed NONE

①