

Revised 4-6-18		CMS#		18142626 OOS PERMIT	
CenturyLink BSW Order/Maintenance Work Authorization					
Company	T600	Exchange Name		Service Order#	out of service!
Work Activity	Fiber-Buried	Capital	N	Maintenance	Y
Customer Name	GEORGE & NOREEN SMITH			Phone#	7634244438
Address	10861 102ND AVE N				
City & Zip	Maple Grove, MN 55369				
Location/Directions	Valley Forge Just north of 610				
Description of Work or Special Instructions	No Temp Customer out of servcie Rush new fiber BSW REPAIR				
Held Order	Y	Permit:	Y	Bore:	Y
Tech Name and Tech #	Ryan to cutover			Employee Contact#	763-464-7242
Sketch	Material/Labor Units			Footage/Quanity	Comments
(Include Cntr Line & Pedestal)	Description	Notes			
Cntr Line foots	33	SEB3-22	BSW-3 & plow plcmt		
Ped#		SEB3-22T	BSW-3 & hand dig plcmt		
Parish/County		SEPCUTOVER	CUTOVER BSW		
		BM83	BSW guard at house		
Township:		XXSEB-GL	Remove temp drop		
Section		BM61(1.25)SEB	BSW Bore footage		170
Range		SEBO PER FT LBR	Fiber & plow plcmt		39
		SEBO PER FT LBR T	Fiber & hand dig plcmt		
		SEB6-22	BSW-6 & plow plcmt		
		BM2(5/8)(8)	Ground Rod		
		Trip Charge	Trip Charge		1
		BM61(3)D-Rock CBL	Rock Boring		
		Permit	Permit		1
Nearest cross st.	Valley Forge Lane			Plat Page	Map#

Estimated Cost

© 2018 Google

Originated By:	Ryan Einerwold	Date:	8/3/18	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					