


## Local CMS#

CMS#

16198184 HELD PERMIT

nt Job Order/Maintenance \	

Company	T866	Exchange	579 C	Osseo						Service Order#		1394526327
Work Activity	Drop-Buried	Copper					Ca	apital	Х	Mainten	ance	
Customer Name	Paul Woodru	ıff								Phone#	763-	-315-2909
Address	10769 WELLINGTON LN N					One Call Ticket#						
Location/Directions	Maple Grove							_		_		
Description of Work or Special Instructions Plow 157 ft from Ped to Nid												
Pick up 200 ft tmp line and cut over when done												
DOR/TOG	Yes No	x Permit:	Yes	No	x Bore: \	Yes_	Χ	No		CBR#		
Employee Name	Kris Townser	nd				_	Emplo	yee Co	ntact#	612-430	3133	
Sketch		Materia	/Labor	Units			Est	Actual		Place	d by	
(Include Line & Pedestal)	Des	scription			Notes		Qty.	Qty		(Foreman/Cr	ew Name	·)
Line												
Ped#												
Parish/County												
Hennipen												
Township:												
Section												
Range												
GPS Reading												
Nearest cross st.							Plat	Page		Map# _		
Damaged facility #	125196		_									1
SKETCH										Tax Code		-N -
												1



Originated By:	Evans	Date:	6/24/16	Completed By:	Date:
Authorized By: (APS)		Date:		Inspected By:	Date:
Authorized By: (AOM)		Date:		<u>-</u>	
Inspection notes:				_	