


Revised 4-6-18		CMS#	18166935 PERMIT		
CenturyLink BSW Order/Maintenance Work Authorization					
Company	T600	Exchange Name	MAPLE GROVE	Service Order#	1506092732
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N
Customer Name	Matthew Hagel		Phone#	7634165103	
Address	18443 70th Ave N		One Call Ticket#		
City & Zip	Maple Grove MN				
Location/Directions					
Description of Work or Special Instructions		Sprinkler system			
Held Order	N	Permit:	Y	Bore:	Y
Tech Name and Tech #	Roy Miller ab62842		Employee Contact#	612-219-9122	
Sketch	Material/Labor Units		Footage/Quantity	Comments	
(Include Cntr Line & Pedestal)	Description	Notes			
Cntr Line footg	33	SEB3-22	BSW-3 & plow picmt		
		SEB3-22T	BSW-3 & hand dig picmt		
Ped#	A0G2Z	SEPCUTOVER	CUTOVER BSW	1	
Parish/County	Hennepin	BM83	BSW guard at house	1	
		XXSEB-GL	Remove temp drop	400	
Township:		BM61(1.25)SEB	BSW Bore footage	80	
Section		SEBO PER FT LBR	Fiber & plow picmt		
Range		SEBO PER FT LBR T	Fiber & hand dig picmt	62	
		SEB6-22	BSW-6 & plow picmt		
		BM2(5/8)(8)	Ground Rod		
		Trip Charge	Trip Charge	1	
		BM61(3)D-Rock CBL	Rock Boring		
		Permit	Permit	1	
Nearest cross st.	Vagabond ave		Plat Page		Map#

Estimated Cost

--



Originated By: Roy Miller Date: 9/4/18 Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Email sketch to: MetroBSW@Centurylink.com

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection		
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker		