


Revised 4-6-18		CMS#	18195049 HELD PERMIT		
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>					
Company	T600	Exchange Name	MAPLE GROVE	Service Order#	1415370267
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N
Customer Name	James Rodriguez		Phone#		
Address	10715 Sundance Blvd		One Call Ticket#		
City & Zip	Maple Grove, MN				
Location/Directions					
Description of Work or Special Instructions					
Held Order	Y	Permit:	Y	Bore:	Y
Tech Name and Tech #	Les Peterson AA09419		Employee Contact#		
CBR#	763-807-0943				
Sketch	Material/Labor Units		Footage/Quantity	Comments	
(Include Cntr Line & Pedestal)	Description	Notes			
Cntr Line foot	33	SEB3-22	BSW-3 & plow plcmt		
		SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	10723	SEPCUTOVER	CUTOVER BSW		
Parish/County	Hennep	BM83	BSW guard at house	1	
		XXSEB-GL	Remove temp drop		
Township:		BM6I(1.25)SEB	BSW Bore footage	90	
Section		SEBO PER FT LBR	Fiber & plow plcmt	30	
Range		SEBO PER FT LBR T	Fiber & hand dig plcmt		
		SEB6-22	BSW-6 & plow plcmt		
		BM2(5/8)(8)	Ground Rod		
		Trip Charge	Trip Charge	1	
		BM6I(3)D-Rock CBL	Rock Boring		
		Permit	Permit	1	
Nearest cross st.	Orchid LN		Plat Page	Map#	

Estimated Cost

--



Originated By:		Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					