


Revised 4-6-18		CMS#	18207749 - HELD
<b>CenturyLink BSW Order/Maintenance Work Authorization</b>			
Company	T600	Exchange Name	MAPLE GROVE
Work Activity	Fiber-Buried	Capital	Y
Customer Name	Catherine Krentz	Service Order#	1514737127
Address	6713 Merrimac Ln	Maintenance	N
City & Zip	Maple Grove MN 55311	Phone#	
Location/Directions			
Description of Work or Special Instructions			

Held Order	Y	Permit:	Y	Bore:	Y	CBR#	763-807-0943
Tech Name and Tech #	Les Peterson AA09419			Employee Contact#			

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot#	33	SEB3-22		BSW-3 & plow plcmt
		SEB3-22T		BSW-3 & hand dig plcmt
Ped#	1443-9009	SEPCUTOVER		CUTOVER BSW
Parish/County	Hennepin	BM83	1	BSW guard at house
		XXSEB-GL		Remove temp drop
Township:		BM61(1.25)SEB	170	BSW Bore footage
Section		SEBO PER FT LBR	75	Fiber & plow plcmt
Range		SEBO PER FT LBR T		Fiber & hand dig plcmt
		SEB6-22		BSW-6 & plow plcmt
		BM2(5/8)(8)		Ground Rod
		Trip Charge	1	Trip Charge
		BM61(3)D-Rock CBL		Rock Boring
		Permit	1	Permit
Nearest cross st.	67th Ave		Plat Page	Map#



Originated By:		Date:		Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					