


Permit

Revised 4-6-18		CMS#	18208752	
CenturyLink BSW Order/Maintenance Work Authorization				
Company	T600	Exchange Name	OSSEO	
Work Activity	Drop-Buried Copper		Capital	N
Customer Name	Jeff Joseph		Phone#	7634253231
Address	9935 Union Terrace Ln N		One Call Ticket#	
City & Zip	Maple Grove MN			
Location/Directions	Description of Work or Special Instructions			
	Replow drop. Cut. 125 ft from ped to Nid. 85 ft of right of way			

Held Order	N	Permit:	Y	Bore:	Y	CBR#	6126163032
Tech Name and Tech #	Don Evans		Employee Contact#	6124303133			

Sketch (Include Cntr Line & Pedestal)	Material/Labor Units		Footage/Quantity	Comments
	Description	Notes		
Cntr Line foot	33	SEB3-22	BSW-3 & plow picmt	
		SEB3-22T	BSW-3 & hand dig picmt	
Ped#		SEPCUTOVER	CUTOVER BSW	1
Parish/County		BM83	BSW guard at house	
		XXSEB-GL	Remove temp drop	1
Township:		BM61(1.25)SEB	BSW Bore footage	85
Section		SEBO PER FT LBR	Fiber & plow picmt	
Range		SEBO PER FT LBR 1	Fiber & hand dig picmt	40
		SEB6-22	BSW-6 & plow picmt	
		BM2(5/8)(8)	Ground Rod	
		Trip Charge	Trip Charge	1
		BM61(3)D-Rock CBL	Rock Boring	
		Permit	Permit	1
Nearest cross st.			Plat Page	Map#



Originated By:	Don Evans	Date:	10/31/18	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:				Date:	
Email sketch to:	MetroBSW@Centurylink.com						

1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	