

Company	T600	Exchange Name	OSSEO	Service Order#	
Work Activity	Fiber-Buried	Capital	Y	Maintenance	N
Customer Name	IRENE LENMARK			Phone#	7633151811
Address	8536 OAKVIEW WAY N				
City & Zip	MAPLE GROVE, MN 55369-4789				
Location/Directions	GPS				
Description of Work or Special Instructions	SEE SKETCH FOR DETAILS				

Held Order	N	Permit:	Y	Bore:	Y	CBR#	763-439-5171
Tech Name and Tech #	Mike Rodriguez (aa10109)			Employee Contact#	7632288645		

Sketch		Material/Labor Units		Footage/Quantity	Comments		
(Include Cntr Line & Pedestal)		Description	Notes				
Cntr Line foot	33	SEB3-22	BSW-3 & plow plcmt				
Ped#	mst	SEB3-22T	BSW-3 & hand dig plcmt				
Parish/County	Hennepin	SEPCUTOVER	CUTOVER BSW	1			
		BM83	BSW guard at house	1			
Township:	NA	XXSEB-GL	Remove temp drop	350			
Section		BM61(1.25)SEB	BSW Bore footage	90			
Range	NA	SEBO PER FT LBR	Fiber & plow plcmt	160			
		SEBO PER FT LBR T	Fiber & hand dig plcmt				
		SEB6-22	BSW-6 & plow plcmt				
		BM2(5/8)(8)	Ground Rod				
		Trip Charge	Trip Charge	1			
		BM61(3)D-Rock CBL	Rock Boring				
		Permit	Permit	1			
Nearest cross st.	GPS			Plat Page	NA	Map#	NA



Originated By:	AA10109	Date:	12/6/18	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					

Email sketch to:	MetroBSW@Centurylink.com		
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection	
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker	



