

Revised 4-6-18				CMS#		19012593 held	
CenturyLink BSW Order/Maintenance Work Authorization							
Company		T600	Exchange Name MAPLE GROVE			Service Order#	
Work Activity		Fiber-Buried		Capital	Y	Maintenance	N
Customer Name		Centurylink Simple pay			Phone#		763-315-2938
Address		12360 85th PI N			One Call Ticket#		
City & Zip		Maple Grove MN 55369					
Location/Directions							
Description of Work or Special Instructions							
Held Order		Y	Permit:	Y	Bore:	Y	CBR# 763-370-9416
Tech Name and Tech #		Roy Miller ab62842			Employee Contact#		612-219-9122
Sketch <small>(Include Cntr Line & Pedestal)</small>		Material/Labor Units		Footage/Quantity		Comments	
		Description		Notes			
Cntr Line foot	33	SEB3-22		BSW-3 & plow plcmt			
		SEB3-22T		BSW-3 & hand dig plcmt			
Ped#	125478	SEPCUTOVER		CUTOVER BSW			
Parish/County	Hennep	BM83		BSW guard at house			
		XXSEB-GL		Remove temp drop			
Township:		BM61(1.25)SEB		BSW Bore footage		120	
Section		SEBO PER FT LBR		Fiber & plow plcmt			
Range		SEBO PER FT LBR T		Fiber & hand dig plcmt		30	
		SEB6-22		BSW-6 & plow plcmt			
		BM2(5/8)(8)		Ground Rod			
		Trip Charge		Trip Charge		1	
		BM61(3)D-Rock CBL		Rock Boring			
		Permit		Permit		1	
Nearest cross st.		Mongolia AVE			Plat Page		Map#



Originated By: **Roy Miller** Date: **4/21/19** Completed By: _____ Date: _____
 Authorized By: (APS) _____ Date: _____ Inspected By: _____ Date: _____
 Authorized By: (AOM) _____ Date: _____
 Email sketch to: MetroBSW@Centurylink.com

1. Distance of the bury in Right-of-Way	3. Distance to the nearest intersection
2. Distance from the terminal to the centerline	4. Nearest State Hwy mile marker