



Local
CMS#

CMS# 16201502 HELD / PERMIT


CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order# _____
 Work Activity **Drop-Buried Copper** Capital x Maintenance _____
 Customer Name Richard Drake Phone# 763-315-5846
 Address 10557 WELLINGTON LN N One Call Ticket# _____
 Location/Directions Maple Grove, MN
 Description of Work or Special Instructions plow 200' with 2 30' bores from NID to ped.

DOR/TOG Yes ___ No x Permit: Yes ___ No x Bore: Yes ___ No x CBR# 763-267-2750
 Employee Name Kris Townsend Employee Contact# 612-715-9060

Sketch (Include Line & Pedestal)	Material/Labor Units		Est Qty.	Actual Qty.	Placed by (Foreman/Crew Name)
	Description	Notes			
Line _____					
Ped# _____					
Parish/County Hennipen					
Township: _____					
Section _____					
Range _____					
GPS Reading _____					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____ Tax Code _____
SKETCH |
-N-
|



Wellington LN. N. M. Grove

Originated By: Townsend	Date: 9/6/16	Completed By: _____	Date: _____
Authorized By: (APS) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (AOM) _____	Date: _____	_____	_____
Inspection notes: _____	_____		
