

Revised 4-6-18		CMS#		19002266	
CenturyLink BSW Order/Maintenance Work Authorization					
Company	T600	Exchange Name	OSSEO	Service Order#	
Work Activity	Drop-Buried Copper	Capital	N	Maintenance	Y
Customer Name	LEROY DAHLBERG			Phone#	7634244103
Address	9925 HEMLOCK WAY N				
City & Zip	MAPLE GROVE, MN				
Location/Directions	GPS				
Description of Work or Special Instructions	SEE SKETCH FOR DETAILS				
Held Order	N	Permit:	Y	Bore:	Y
				CBR#	1111111111
Tech Name and Tech #	Mike Rodriguez (aa10109)			Employee Contact#	7632288645
Sketch	Material/Labor Units			Footage/Quantity	Comments
(Include Cntr Line & Pedestal)	Description	Notes			
Cntr Line foots	33	SEB3-22	BSW-3 & plow plcmt		175
Ped#	544 9031	SEB3-22T	BSW-3 & hand dig plcmt		
Parish/County	Hennepin	SEPCUTOVER	CUTOVER BSW		1
		BM83	BSW guard at house		
Township:	NA	XXSEB-GL	Remove temp drop		
Section		BM61(1.25)SEB	BSW Bore footage		80
Range	NA	SEBO PER FT LBR	Fiber & plow plcmt		
		SEBO PER FT LBR T	Fiber & hand dig plcmt		
		SEB6-22	BSW-6 & plow plcmt		
		BM2(5/8)(8)	Ground Rod		
		Trip Charge	Trip Charge		1
		BM61(3)D-Rock CBL	Rock Boring		
		Permit	Permit		1
Nearest cross st.	GPS			Plat Page	NA
		Map#	NA		

Originated By:	AA10109	Date:	1/11/19	Completed By:		Date:	
Authorized By: (APS)		Date:		Inspected By:		Date:	
Authorized By: (AOM)		Date:					
Email sketch to:	MetroBSW@Centurylink.com						
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection					
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker					