



Local
CMS#

16208434 Permit

CenturyLink Constant Job Order/Maintenance Work Authorization

Company T866 Exchange 579 Osseo Service Order# _____
 Work Activity Drop-Buried Copper Fiber Capital x Maintenance _____
 Customer Name RYAN Martin PAU Phone# _____
 Address 9825 107th Ave N Mark Grove MN One Call Ticket# _____
 Location/Directions _____
 Description of Work or Special Instructions _____

DOR/TOG Yes ___ No x Permit: Yes x No ___ Bore: Yes ___ No X CBR# _____
 Employee Name Brandon Smith ROY Miller Employee Contact# 612-298-7599 612-214-9122

Sketch (Include Line & Pedestal)	Material/Labor Units		Est	Actual	Placed by (Foreman/Crew Name)
	Description	Notes	Qty.	Qty	
Line _____					
Ped# _____					
Parish/County _____					
Hennipen _____					
Township: _____					
Section _____					
Range _____					
GPS Reading _____					

Nearest cross st. _____ Plat Page _____ Map# _____
 Damaged facility # _____ Tax Code _____
 SKETCH _____



Originated By: _____	Date: _____	Completed By: _____	Date: _____
Authorized By: (APS) _____	Date: _____	Inspected By: _____	Date: _____
Authorized By: (AOM) _____	Date: _____		
Inspection notes: _____			